

Abstract

A Coriolis flowmeter for the measurement of a process material requiring an ultra high level of purity. This is achieved by forming the entire Coriolis flowmeter of a PFA plastic material that does not transfer ions from the Coriolis flowmeter to the process material flowing through the flowmeter.